

11-764-4

à traduire



Numéro MOTEUR: TDCM-204302023 CLE: T82 4458 AKKU: TPK44FLY-02000011
31.2 kg
115 kg
--- mm
--- mm
Panasonic
70 - 300 %
810 Wh
4.8 hrs

11-764-3

à traduire



Numéro MOTEUR: TDCM-194501542 CLE: T82 5102 AKKU: TPL40FLY-02000485
31.2 kg
115 kg
--- mm
--- mm
Panasonic
70 - 300 %
810 Wh
4.8 hrs

11-764-1

à traduire



N° série MOTEUR: TDCM-194501607 CLE: T82 5485 AKKU: TPK03FLY-02000457
31.2 kg
115 kg
--- mm
--- mm
Panasonic
70 - 300 %
810 Wh
4.8 hrs

11-764-5

à traduire



N° série MOTEUR: ??? CLE: T82 4522 AKKU: 1910150005014
31.2 kg
115 kg
--- mm
--- mm
Panasonic
70 - 300 %
810 Wh
4.8 hrs

11-764-6

à traduire



N° série MOTEUR: TDCM-194501309 CLE: T82 5124 AKKU: TPK03FLY-02000461
31.2 kg
115 kg
--- mm
--- mm
Panasonic
70 - 300 %
810 Wh
4.8 hrs

11-764-2

à traduire



N° série MOTEUR: TDCM-194501616 CLE: T82 4979 AKKU: TPK03FLY-02000048
31.2 kg
115 kg
--- mm
--- mm
Panasonic
70 - 300 %
810 Wh
4.8 hrs

11-764-7

à traduire



N° série MOTEUR: TDCM-194601831 CLE: T82 7733 AKKU: TPK03FLY-02000591
31.2 kg
115 kg
--- mm
--- mm
Panasonic
70 - 300 %
810 Wh
4.8 hrs

11-764-8

à traduire



N° série MOTEUR: TDCM-194501612 CLE: 1/T82 5517 AKKU: TPK03FLY-02000605
31.2 kg
115 kg
--- mm
--- mm
Panasonic
70 - 300 %
810 Wh
4.8 hrs

11-764-9

à traduire



Numéro MOTEUR: TDCM-194601682 CLE: T82 4530 AKKU: TPK40FLY-02000364
31.2 kg
115 kg
--- mm
--- mm
Panasonic
70 - 300 %
810 Wh
4.8 hrs